

## Manual Defrost for Gelato Case

After long period of operation, even the Gelato case has its own automatic defrosting system it still can accumulate ice. Therefore, for maximum performance and hygiene purpose it is highly recommended to do manual defrost once every two months. This process requires a few hours thus it should be done after the shop is close and leave overnight. The manual defrost procedure is described in steps below:

1. Remove all the gelato
2. Turn off the unit
3. Remove power cable
4. Remove all the GN pans and side bars



5. Remove under covers




6. Open the case door and leave it overnight to become free of accumulated ice



7. Rise the middle part of unit only with maximum 2 cups of water



8. Wipe out the remaining water and inside but please take extreme caution as there are very sharp edges inside. SKIPIO highly recommends end user to wear protective gloves during this process.



9. Assembly the under covers and side bars
10. Turn on the unit and place back Gelato